Local Risk Assessment For: Buggy Use - No Access.	Dept: GOLF	REF: BUG – ST4

Name of Course: Chester Le Street Golf Club.
Name of Person/s Completing This Assessment: Jack Hetherington

Date:

Activity/ Equipment Used	Who is at Risk	What are the Risks	What Control Measures are Required? (Precautions taken to reduce the risks)			
EZ-GO RXV Elite	Machine operator.	Uneven terrain.	All operators must sign and adhere to the buggy policy document. Available in Pro shop.  No buggy access.  All operators to use buggy in accordance with owner's guide. Available in Pro shop.			
	Passenger.	Collision.				
	Staff.	Weather conditions.				
	Contractors.	Overloading.				
	Visitors/Golfers.	Mechanical failure.	All operators must	perators must adhere and follow signs routes provided.		
	Public/Trespassers	Slippery surfaces.	Always drive at a safe speed, be cautious on uneven ground and avoid sudden turns.  Maintain a safe distance from other golfer and vehicles at all times.  Do not overload beyond recommended capacity in owner's guide.  Regularly inspect and maintain vehicle in accordance of owner's guide.  Drive cautiously on wet or slippery surfaces. Reduce speed and avoid sudden breaking or acceleration.			
What is the Overall Risk When the Control Measures are Followed.		Severity	Accident Book	3 Days Off	Major Injury/	
		Likelihaad		Injury	Death	
<mark>1-1</mark>		Likelihood Seldom 1	1	2	3	
		Occasional 2	1	2	3	
		Frequent 3	1	2	3	

This assessment should be reviewed:

- 1. Following an accident or incident 2. Prior to introducing new equipment 3. When changes are made to working practices
- 4. Changes to the Environment.