Local Risk Assessment For: Buggy Use	Dept: GOLF	REF: BUG – ST1

Name of Course: Chester Le Street Golf Club.
Name of Person/s Completing This Assessment: Jack Hetherington

Date:

Activity/ Equipment Used	Who is at Risk	What are the Risks	What Control Measures are Required? (Precautions taken to reduce the risks)			
EZ-GO RXV Elite	Machine operator.	Uneven terrain.	All operators must sign and adhere to the buggy policy document. Available in Pro shop.  All operators to use buggy in accordance with owner's guide. Available in Pro shop.			
	Passenger.	Collision.				
	Staff.	Weather conditions.				
	Contractors.	Overloading.	All operators must a	rators must adhere and follow signs routes provided.		
	Visitors/Golfers.	Mechanical failure.	Always drive at a safe speed, be cautious on uneven ground and avoid sudden turns.			
	Public/Trespassers	Slippery surfaces.	Maintain a safe distance from other golfer and vehicles at all times.  Do not overload beyond recommended capacity in owner's guide.  Regularly inspect and maintain vehicle in accordance of owner's guide.  Drive cautiously on wet or slippery surfaces. Reduce speed and avoid sudden breaking or acceleration.			
What is the Overall Risk When the Control Measures are Followed.		Severity	Accident Book	3 Days Off	Major Injury/	
		Likelihood		Injury	Death	
<mark>1-3</mark>		Seldom 1	1	2	3	
		Occasional 2	1	2	3	
		Frequent 3	1	2	3	

This assessment should be reviewed:

1. Following an accident or incident 2. Prior to introducing new equipment 3. When changes are made to working practices

4. Changes to the Environment.