

Local Risk Assessment For: Buggy Use – Partial medical access	Dept: GOLF	REF: BUG – ST3
---	------------	----------------

Name of Course: Chester Le Street Golf Club.

Date:

Name of Person/s Completing This Assessment: Jack Hetherington

Activity/ Equipment Used	Who is at Risk	What are the Risks	What Control Measures are Required? (Precautions taken to reduce the risks)		
EZ-GO RXV Elite	Machine operator.	Uneven terrain.	<p>All operators must sign and adhere to the buggy policy document. Available in Pro shop.</p> <p>Medical Access to holes 12, 13 & 14. All operators must adhere to S.O.P. available in Pro Shop.</p> <p>All operators to use buggy in accordance with owner's guide. Available in Pro shop.</p> <p>All operators must adhere and follow signs routes provided.</p> <p>Always drive at a safe speed, be cautious on uneven ground and avoid sudden turns.</p> <p>Maintain a safe distance from other golfer and vehicles at all times.</p> <p>Do not overload beyond recommended capacity in owner's guide.</p> <p>Regularly inspect and maintain vehicle in accordance of owner's guide.</p> <p>Drive cautiously on wet or slippery surfaces. Reduce speed and avoid sudden breaking or acceleration.</p>		
	Passenger.	Collision.			
	Staff.	Weather conditions.			
	Contractors.	Overloading.			
	Visitors/Golfers.	Mechanical failure.			
	Public/Trespassers	Slippery surfaces.			
What is the Overall Risk When the Control Measures are Followed. <p style="text-align: center;">2-3</p>	Severity		Accident Book	3 Days Off Injury	Major Injury/ Death
	Likelihood				
	Seldom 1		1	2	3
	Occasional 2		1	2	3
Frequent 3		1	2	3	
This assessment should be reviewed: 1. Following an accident or incident 2. Prior to introducing new equipment 3. When changes are made to working practices 4. Changes to the Environment.					